



SWEETWATER AUTHORITY

505 GARRETT AVENUE
POST OFFICE BOX 2328
CHULA VISTA, CALIFORNIA 91912-2328
(619) 420-1413
FAX (619) 425-7469
<http://www.sweetwater.org>

GOVERNING BOARD

TERESA "TERRY" THOMAS, CHAIR
RON MORRISON, VICE CHAIR
JOSIE CALDERON-SCOTT
STEVE CASTANEDA
JOSÉ F. CERDA
JOSE PRECIADO
JESS VAN DEVENTER

JAMES L. SMYTH
GENERAL MANAGER

JENNIFER H. SABINE
ASSISTANT GENERAL MANAGER

April 27, 2017

National School District
Christopher B. Carson
Business Services
1500 N Ave
National City, CA 91950

RE: Lead Test Results

Dear Mr. Carson:

As you are aware (via recent correspondences with Sweetwater Authority), the initial round of lead sampling has been completed for the ten public elementary schools in the National School District (NSD) under the California State Water Resources Control Board, Division of Drinking Water (State Board-DDW) Lead in Schools Monitoring Program. A summary of the lead test results for the NSD elementary schools is provided in Attachment 1. Five drinking water locations per school were sampled, representing the highest use drinking fountains or faucets at each school. Only one sample result for lead (Harbison School sample ID 3710025-AAF-A; 20 ppb) was detected above the State Board-DDW Lead Action Level of 15 ppb (parts per billion).

As per the Lead in Schools Monitoring program, sample sites that have lead test results that are less than the Lead Action Level are suitable for consumption and no further action is required. For sample sites where lead is detected greater than the Action Level of 15 ppb, the school must decide what corrective action will be taken. Information regarding follow-up sampling and corrective actions is available on the State Board-DDW Lead in Schools website, at the following link:

http://www.waterboards.ca.gov/drinking_water/certlic/drinkingwater/leadsamplinginschools.shtml

Please call me at 619-409-6813 (or e-mail mhatcher@sweetwater.org) to further discuss NSD corrective action/follow-up sampling options for Harbison School sample 3710025-AAF-A.

Sincerely,

Mark D. Hatcher
Laboratory Supervisor/Regulatory Analyst
Sweetwater Authority

Attachment I
State Board, Division of Drinking Water - Lead in Schools Testing Program
Sweetwater Authority Summary of Lead Testing Results - National School District

School	Sample Site ID	Location Description	Sample Date	Lead Test Results (ppb) ¹	Action Level Exceeded? ² (Yes/No)
Lincoln Acres School	3710025-AAB-A	Kitchen (3 basin sink)	4/12/2017	ND	No
Lincoln Acres School	3710025-AAB-B	Western end outside restrooms adjacent to Rm. 11 (middle bubbler)	4/12/2017	ND	No
Lincoln Acres School	3710025-AAB-C	Eastern side of bldg. (next to Room 9B; left bubbler)	4/12/2017	ND	No
Lincoln Acres School	3710025-AAB-D	Northern Exterior side of building (outside Room 1B; far right bubbler)	4/12/2017	ND	No
Lincoln Acres School	3710025-AAB-E	Eastern end of bldg. outside of restrooms next to Rm. 21 (far right bubbler)	4/12/2017	ND	No
John Otis School	3710025-AAC-A	Northern Exterior of Western end outside of Girls restroom (far right bubbler)	4/12/2017	ND	No
John Otis School	3710025-AAC-B	Southern Exterior by Room 11 (left bubbler)	4/12/2017	5	No
John Otis School	3710025-AAC-C	Northern Exterior on the Eastern end outside of Boys restroom (far right bubbler)	4/12/2017	ND	No
John Otis School	3710025-AAC-D	Kitchen (3 basin sink)	4/12/2017	ND	No
John Otis School	3710025-AAC-E	Northeastern corner of bldg. (lower right bubbler)	4/12/2017	ND	No
Kimball School	3710025-AAD-A	Exterior of bldg. by room 4 (right bubbler)	4/12/2017	8	No
Kimball School	3710025-AAD-B	Western Exterior of bldg by room 3 (far left bubbler)	4/12/2017	ND	No
Kimball School	3710025-AAD-C	Southern Exterior next to room 10 by Boys restroom (left bubbler)	4/12/2017	ND	No
Kimball School	3710025-AAD-D	Kitchen (3 basin sink, right faucet)	4/12/2017	ND	No
Kimball School	3710025-AAD-E	Wester Exterior of bldg. (left bubbler)	4/12/2017	ND	No
El Toyon School	3710025-AAE-A	Inside kitchen (3-basin sink)	4/11/2017	ND	No
El Toyon School	3710025-AAE-B	Boys and Girls restroom adjacent to Room 7 (right side bubbler)	4/11/2017	ND	No
El Toyon School	3710025-AAE-C	South side adjacent to Room 17 (far left bubbler)	4/11/2017	ND	No
El Toyon School	3710025-AAE-D	South Exterior between Admin and Lounge (left bubbler)	4/11/2017	6	No
El Toyon School	3710025-AAE-E	South exterior between K3 and K4 (right bubbler)	4/11/2017	ND	No
Ira Harbison School	3710025-AAF-A	Southern Exterior of bldg. (far left bubbler)	4/11/2017	20	Yes
Ira Harbison School	3710025-AAF-B	North End of bldg. by Multi-purpose bldg. (far left bubbler)	4/11/2017	7	No
Ira Harbison School	3710025-AAF-C	Kitchen (3 basin sink right faucet)	4/11/2017	ND	No
Ira Harbison School	3710025-AAF-D	Restroom Exterior by Room 7 (left fountain right bubbler)	4/11/2017	10	No
Ira Harbison School	3710025-AAF-E	Upper Playground (far right bubbler)	4/11/2017	6	No

State Board, Division of Drinking Water - Lead in Schools Testing Program
Sweetwater Authority Summary of Lead Testing Results - National School District

School	Sample Site ID	Location Description	Sample Date	Lead Test Results (ppb) ¹	Action Level Exceeded? ² (Yes/No)
Central School	3710025-AAG-A	Inside kitchen (3-basin sink faucet)	4/11/2017	ND	No
Central School	3710025-AAG-B	East side of bldg. (right bubbler)	4/11/2017	10	No
Central School	3710025-AAG-C	West end of bldg. between Boys and Girls restrooms (right bubbler)	4/11/2017	ND	No
Central School	3710025-AAG-D	East end of bldg. between Boys and Girls restrooms (right bubbler)	4/11/2017	ND	No
Central School	3710025-AAG-E	P3 North fence of play area (outside fence lower bubbler)	4/11/2017	ND	No
Las Palmas School	3710025-AAH-A	Southern side of bldg. by Room 10 (far left bubbler)	4/12/2017	ND	No
Las Palmas School	3710025-AAH-B	Southern Exterior corner of bldg. by stage (far right bubbler)	4/12/2017	ND	No
Las Palmas School	3710025-AAH-C	Kitchen (3 basin sink right faucet)	4/12/2017	ND	No
Las Palmas School	3710025-AAH-D	Eastern Exterior corner of bldg. (far right bubbler)	4/12/2017	ND	No
Las Palmas School	3710025-AAH-E	West Exterior of bldg. (far left bubbler)	4/12/2017	ND	No
Olivewood School	3710025-AAI-A	Kitchen (3 basin sink right faucet)	4/12/2017	ND	No
Olivewood School	3710025-AAI-B	Northeastern corner of bldg. exterior (far left bubbler)	4/12/2017	ND	No
Olivewood School	3710025-AAI-C	West end of bldg. (far left bubbler)	4/12/2017	ND	No
Olivewood School	3710025-AAI-D	Eastern side of bldg. exterior in center (left bubbler)	4/12/2017	ND	No
Olivewood School	3710025-AAI-E	East end of bldg. (far left bubbler)	4/12/2017	ND	No
Palmer Way School	3710025-AAJ-A	Outside of PS-1 in playground area (lowest bubbler)	4/11/2017	ND	No
Palmer Way School	3710025-AAJ-B	West Exterior of bldg. between Boys and Girls restrooms (far lower left bubbler)	4/11/2017	ND	No
Palmer Way School	3710025-AAJ-C	Northern Exterior of bldg. (far right bubbler)	4/11/2017	ND	No
Palmer Way School	3710025-AAJ-D	Between bldg. rooms B2 and C5 (far right bubbler)	4/11/2017	5	No
Palmer Way School	3710025-AAJ-E	Kitchen (3-basin sink right faucet)	4/11/2017	ND	No
Rancho de la Nacion School	3710025-ABA-A	Outside of Boys and Girls restroom (right side of bubbler)	4/11/2017	ND	No
Rancho de la Nacion School	3710025-ABA-B	Outside of Boys and Girls restroom (left bubbler)	4/11/2017	5	No
Rancho de la Nacion School	3710025-ABA-C	Northern side of bldg. (left side bubbler)	4/11/2017	ND	No
Rancho de la Nacion School	3710025-ABA-D	Kitchen (3-basin sink)	4/11/2017	ND	No
Rancho de la Nacion School	3710025-ABA-E	Inside classroom 11	4/11/2017	ND	No

¹ND = Not Detected

²The California Action Level for lead is 15 ppb ; no corrective actions are required for lead test results ≤ 15 ppb.